


# Connection cable voltage

For devices of the IKI series and ohmic sensors

This connection cable can be used to connect devices of the IKI-50 series to sensors (For the connection to the ohmic sensor, a coaxial cable set is additionally required).



## Features

Switch for dividing the Y-cable into two strands.

## Versions

Item number	Description
2500483	Adapter switch   1F to 2F   0.2 m
2500483_H001	Adapterweiche   1F auf 2F   0,4 m
2500483_H015	Adapterweiche   1F auf 2F   1,5 m

## Technical Data

### General data

Article number	2500483_H001
Quantity unit	Piece
Product designation	Adapterweiche   1F auf 2F   0,4 m

### Dimensions and type of installation

Total length L	0 m
----------------	-----

### Operating conditions

Operating temperature	-25°C ... 55°C
Storage temperature	-30°C ... 75°C

