For universal tester CAP-Phase

The bag conveniently accommodates the CAP-Phase universal tester, a set of HR/LRM adapters and a measuring cable set. The bag is particularly suitable for mobile use in the field.



Scope of delivery

This item is exclusively the shoulder bag itself

Technical Data

General data

Article number	3501101	
Product designation	Shoulder bag for CAP-Phase	
Operating conditions		
Operating temperature	-25°C 55°C	
Storage temperature	-30°C 70°C	